



Confetti Effects by  
Special Effects Systems, Inc.

## Electric Base Mount Confetti Cannon



◀ 1. Turn the knob on the piercing unit to the off position shown to the left.



◀ 2. Quickly screw the co2 cylinder into the piercing unit. (Some gas may escape but this is normal)



◀ 3. Attach the piercing unit to the quick connect as shown. Pull on the piercing unit to make sure it is secure.



◀ 4. Attach the loaded barrel to the quick connect as shown. Pull on the barrel to make sure it is secure. Attach the safety cable to the barrel.

◀ 5. Slowly turn the piercing unit knob to the on position. Your confetti cannon is now loaded and charged.

6. Plug the confetti cannon into a power strip with the power off. When you are ready to fire the confetti or streamers, turn the power strip on for 3-5 seconds.  
**IMPORTANT:**  
Turn the power on for at least 3-5 seconds or the confetti cannon will not fire properly.

Never aim the confetti cannon at anyone.  
Never leave the confetti cannon unattended after attaching co2 cylinder.  
Never hold or fire the confetti cannon in front of your face.  
Never hold or fire the confetti cannon above your head.  
Do not touch co2 cylinder immediately after firing. It becomes extremely cold.

## Barrel Loading 1 inch



◀ 1. Cut the end of the sleeve.



◀ 2. Slide the open end of the sleeve into the barrel.



◀ 3. Take hold of the plastic sleeve.



◀ 4. Slide the confetti or streamers into the barrel. Remove the plastic sleeve completely.



◀ 5. Place a compression cap onto the end of the barrel.



◀ 6. Use compression tape around the barrel and cap. Never tape over end of barrel!



◀ 7. Use thumb to create a good seal on the compression tape.