



Confetti Effects by
Special Effects Systems, Inc.


Centerpiece Prop Confetti Cannon Instructions




◀ 1. Unscrew the top brass fitting from the solenoid as shown.



◀ 2. Leave the silver washer on the solenoid as shown.



◀ 3. Place the tray on top of the solenoid as shown. Push the brass threads up through the hole in the tray.



◀ 4. Screw the quick connect fitting onto the brass threads as shown. Hand tighten the quick connect fitting.



◀ 5. Make sure the piercing unit is in the closed position as shown before screwing in co2 cylinder.



◀ 6. Quickly screw the co2 cylinder into the piercing unit. Make sure to screw the co2 cylinder completely into the piercing unit.



◀ 7. Attach the loaded piercing unit to the quick connect on the solenoid as shown.



◀ 8. Turn the piercing unit knob to the on position as shown.



◀ 9. Place a receiver with new batteries into the bowl. Plug the receiver into the solenoid. Turn the receiver on.



◀ 10. Place the tray on top of the bowl and attach the barrel to the quick connect as show.



◀ Everything is now ready for you to place your own floral arrangement onto the unit.

Always use new 9 volt batteries in the receivers. Once the receivers are turned on they have a life of 24 hours.

The transmitter has a range of 500 feet with line of sight.